

RECEIVING INSPECTION REPORT

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080047-2

No. 11552

RECEIVED FROM

PLANT 49

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED ON STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OFFER NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
3	322	C	124	C	10					
DRAWING NO. AND DESCRIPTION:										QUANTITY ACCEPTED REJECTED
731192-B Cover Camera										3 ✓
IPB 00752										

RECEIVED BY *Bancos* INSPECTED BY *Duca* DATE 3/16/57REJECTS RETURNED
ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961 E. COLORADO ST., PASADENA, CALIF.

No. 11612

RECEIVED FROM

PLANT 49

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO.	DRAWING NUMBER	DWG. BASED ON STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OFFER NUMBER	BUY OUT CODE NO.	ACCT. OR W.O. NO.	REMARKS
20	322	C	100	C	13					
DRAWING NO. AND DESCRIPTION:										QUANTITY ACCEPTED REJECTED
731403-A -pneum I/O Mount										20 ✓
IPB 02767										

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080047-2

RECEIVED BY *Bancos* INSPECTED BY *Duca* DATE 3/18/57REJECTS RETURNED
ON SHIP MEMO NO.